Enrollment N	0:		Exam Seat No:			_
	C.U	SHAH UN	NIVERSI	$\Gamma \mathbf{Y}$		
		mmer Exam				
Subject Name	: Mechanica	l Drafting				
Subject Code: 2TE03MDR1			Branch: Diploma (Mechanical)			
Semester: 3		04/04/2018	Time: 02:30 To 0		Marks: 70	
Instructions:						
(2) Instruction (3) Draw	ctions written	le calculator & any oth on main answer book and figures (if necessa a if needed.	are strictly to be obey		rohibited.	
Atter	npt the follow	ving questions:				(1
a) The fu	ıll form of BIS	is,				
Stand	ard	B) Bureau of Indian Standard arcs in drawing sheet,	C) Basic Indian Standard	,	ureau of igent Standard	
,	vider is used.	~	C) Stoke	D) ba	ar	
c) In a S A) 45		ngles are 30° and 60°, w B) 100°.	while third angle is,	D) 12	20°	
d) Dimer	nsions of a title	block is,				
	5 x 45 mm.	B) 185 x 65 mm.	C) 185 x 55 mm.	D) 18	85 x 75 mm	
,	rawing, scale is alf scale.	shown 1:5, it indicates t B) enlarging scale.	the scale is C) reducing scale	D) fo	ıll scale	
f) In a fr		h dimensions can be rea	nd from the following,	D) no	one of the	
g) How	many mavimi	ım views can be drawr	n in multi views repr	above esentatio		
g) How A) th	_	B) four	C) five	D) si		
,		f surface of a cylinder	,	,		
A) cir i) Which		B) square s a permanent one from	C) triangle the following?	D) re	ectangle	
,	nt of screw	B) adhesive joint	C) riveted joint	D) no	one of the one	

Q-1

fasteners

A) parallel

drawing

A) Computer Aided

j)

k)

1)

In piping, an elbow is used to join two pipes at,

What is the meaning of CAD in AutoCAD?

B) right angle

Drafting

B) Computer Aided

To remove unwanted lines in AutoCAD which command is used?



C) inclined

Designing

C) Computer Aided

D) none of the one

D) all of the above

	m)		B) Trim in AutoCAD which cor		D) Hatch	
	n)	A) Line Which command const	B) Trim tructs an object parallel	C) Copy for the selected object a	D) Hatch	
	11)	A) offset command	B) trim command	C) line command.	D) hatch command.	
Attemp	t any f	our questions from (Q-2 to Q-8			
Q-2	1	Attempt all questions A cube of 30 mm sides is held on one of its corners on HP such that the bottom square face containing that corner is inclined at 300 to HP. Two of its adjacent base edges containing the corner on which it rests are equally inclined to VP. Draw the				10
	2	top and front views of List the types of secti	or the cube. ions and sketch any or	ne type.		4
Q-3	1	Attempt all questions A hexagonal pyramid has an altitude of 60 mm and side base 30mm. The pyramid rests on one of its side of the base on HP such that the triangular face containing that side is perpendicular to HP. Draw the front and top views.				10
	2	Draw the surface rought (1) Surface rought (2) Sampling leng (3) Direction of la (4) Machining alle	ghness symbol showinness limit: 6.3 μ m.	ng the following detai	ls in it.	4
Q-4 1		Attempt all questions Draw the top and front views of a rectangular pyramid of sides of base 40x 50 mm and height 70 mm when it lies on one of its larger triangular faces on HP. The longer edge of the base of the triangular face lying on HP is inclined at 600 to VP in the top view with the apex of the pyramid being nearer to VP.				10
	2	Draw the surface rought (1) Surface rought (2) Sampling leng (3) Direction of la (4) Machining alle	ghness symbol showing the symbol showing the symbol showing the symbol showing the symbol sym	ng the following detai s.	ls in it.	4
Q-5 1		Attempt all questions A cone of base 80 mm diameter and height 100 mm lies with one of its generators on HP and the axis appears to be inclined to VP at an angle of 400 in the top view. Draw its top and front views.				10
	2	Draw the following p		on. (4) Reduce	r.	4
Q-6	1	Attempt all question Detailed component fig. 1. Draw its assen	parts of a knuckle joir	nt are shown by their l	sometric drawing in	10
	2	Explain types of fits.	•	6		4
			0 11			



Q-7	1 2	Attempt all questions Fig. 2 shows the assembly drawing of cotter joint with sleeve, prepare its detailed drawing. List at least four AutoCAD commands and state their usage				
Q-8	1 2	List at least four AutoCAD commands and state their usage. Attempt all questions Draw a symbol used to show complete information for welding and mention all information in symbol. Draw the following welding symbols. (1) Fillet weld. (2) Spot weld. (3) Seam weld (4) Square butt weld				
			ગુજરાતી			
Q-1		Attempt the following questions:				
	a)	BIS नुं पूरुं नाम शुं छे? A) British India B) Bureau Standard Standard	Standard	intelligent Standard		
	b)	ડ્રોઇંગ શીટ્માં વર્તુળ અને યાપ દોરવ A) divider is used. B) compass		D) bar		
	c)	સેટ સ્ક્વેરબે ખૂણા 30° અને 60° ના હે A) 45°. B) 100°.	ોય છે, તો ત્રીજો ખૂણો કેટલાનો C) 90°	ફર્શ? D) 120°		
	d)	ટાઈટલ બ્લોકના માપ શું છે? A) 185 x 45 mm. B) 185 x 65	5 mm. C) 185 x 55 mr	m. D) 185 x 75 mm		
	e)	ડ્રોઈંગમાં સ્કેલ ૧:૫ દર્શાવ્યો છે, તો દ A) અડધો સ્કેલ. B) વધતો ર	ર્શાવેલ સ્કેલ કયો સ્કેલ છે?			
	f)	ફ્રન્ટ વ્યૂમાં નીચેનામાંથી કયા પરિમાણ	•			
	g)	પહાળાઇ મલ્ટીવ્યૂ ની રજુઆતમાં મહત્તમ કેટલા	ા વ્યૂ દોરી શકાય છે?			
	h)	A) ત્રણ B) યાર નળાકારની સપાટીનું ડેવેલોપમેન્ટ કેવું	C) પાંચ ું હશે?	D)		

i) નીચેનામાંથી કયો જોઈન્ટ કાયમી છે?

A) સ્ક્રૂ ફાસ્નર્સ નો B) એડફેસિવ જોઈન્ટ

B) ચોરસ

) એડફેસિવ જોઈન્ટ C) રિવેટેડ જોઈન્ટ

C) ત્રિકોણ

D) એક પણ નહિ

D) લંબચોરસ

જોઈન્ટ

A) વર્તુળ

j) In piping, an elbow is used to join two pipes at,



		પાઈપીંગમાં એલ્બોકેવી બે પાઈપને	જોડવા વપરાય છે?					
		A) સમાંતર B) કાટ ખૂ	ણે C) ત્રાંસી	D) એક પણ નહિ				
	k)	AutoCADમાં CADનો અર્થ શું થાય	છે?					
	1)	A) Computer Aided B) Computer Aided B) Computer Aided B) Computer Aided B of Computer Aided A						
		A) લાઈન B) ટ્રીમ	C) ક્રોપી	D) ફેત્ય				
	m)	એક સરખી આકૃતિ દોરવા માટે Auto	CADમાં કથો કમાન્ડ વપરાય) ?				
		A) લાઈન B) ટ્રીમ	C) ક્રોપી	D) ફેત્ય				
	n)	નીચેનામાંથી કયો કમાન્ડ પસંદ કરેલ	ા ઓબ્જેક્ટને સમાંતર આપેલા	અંતરે બીજો ઓબ્જેક્ટ દોરી આપે				
		છે?						
		A) ઓફસેટ કમાન્ડ B) ટ્રીમ ક	માન્ડ C) લાઈન કમા	ન્ડ D) હેત્ય કમાન્ડ				
บ-5 ขโ	l u.z :	નાંથી કોઈ પણ યાર પ્રશ્ <u>નો</u> ના જ	ગાળ લામી					
प्र-र या	l y-C -	નાંચા કાંઇ પણ ચાર પ્રશ્નાના જ	તાબ લખા.					
Q-2		નીચેના પ્રશ્નોના જવાબ આપો.						
	1	30 મીમી બાજુવાળો એક સમધન તેનો એક ખૂણો HP પર છે, જેથી તે ખૂણાને સમાવતી તળિયાની						
		ચોરસ બાજુ HP સાથે 30° નો ખૂણો બનાવે છે. ખૂણાને સમાવતી બે બાજુની કિનારીઓ કે જેના પર						
	સમધન ઉભો છે તે પણ VP સાથે તેટલો જ ખૂણો બનાવે છે. સમધનના ટોચ અને ફ્રન્ટ દેખાવો દોરો.							
	2	સેક્શનના પ્રકારો લખો અને કોઈ પણ	્રા એક પ્રકાર દોરો.		4			
Q-3		નીચેના પુશ્નોના જવાબ આપો.						
Q U	1	એક ષટકોણ પીરામીડ જેની ઊંચાઈ ૬૦ મીમી અને સાઈડ બેઝ ૩૦ મીમી છે. પીરામીડ તેની એક બાજુ						
		HP પર રાહ તે રીતે ઉભો છે જેથી ટે બાજુને સમાવતી ત્રિકોણાકાર સપાટી HPને લંબ થાય. ટોચના અને						
		ફ્રન્ટ દેખાવો દોરો.						
	2	भीगुमी विभाग स्वातिमी मञ्हम उह	ച്ചപ്പെട്ടി		4			
	_	નીચેની વિગતો દર્શાવતી સરફેસ રફનેસની સંજ્ઞા દોરો. (1) સરફેસ રફનેસની સીમા : ૬.૩ માઇક્રોન્સ						
		(2) સેમ્પલનીલંબાઇ :૫૦ મિમિ.						
		(3) લેયરનીદિશા :ગોળાકાર(Circ	ular).					
		(4) મશિનીંગએલાવન્સ :૨.૫મિમિ	,					
		(5) સરફેસ બનાવવાની પધ્ધતિ	: ગ્રાઈન્ડીંગ (Grinding).					
Q-4		નીચેના પ્રશ્નોના જવાબ આપો.						
	1	४० mm x ५० mm બાજુ અને ૭૦ r	nm ઊંચાઈ ધરાવતા લંબચોરસ	. પીરામીડનાં ટોચના અને સામેના	10			



(ફ્રન્ટ) દેખાવો દોરો કે જ્યારે તેની મોટી ત્રિકોણાકાર બાજુ HP પર રહેલી હોય. HP પર રહેલી મોટી ત્રિકોણાકાર બાજુ ટોયમાંથી જોતા VPની નજીક રહેલા પીરામીડના શિરોબિંદુ સહીત VP સાથે 50° નો ખૂણો બનાવે છે.

	2	નીચેની વિગતો દર્શાવતી સરફેસ રફનેસની સંજ્ઞા દોરો.	4			
		(1) સરફેસ રફનેસની સીમા : ૧૨ માઇક્રોન્સ				
		(2) સેમ્પલનીલંબાઇ :૫ મિમિ.				
		(3) લેયરનીદિશા :સમાંતર(Parallel).				
		(4) મશિનીંગએલાવન્સ :૨.૫મિમિ.				
		(5) સરફેસ બનાવવાની પધ્ધતિ : મિલીંગ (Milling).				
Q-5		નીચેના પ્રશ્નોના જવાબ આપો.				
	1	૮૦ mm વ્યાસ અને ૧૦૦ mm ઊંચાઈ ધરાવતો એક શંકુનો એક જનરેટર HP પર રહેલો છે અને શંકુની				
		અક્ષીસ ટોપ વ્યૂમાં VP સાથે ૪૦° નો ખૂણો બનાવે છે. તો ટોચના દેખાવો અને ફ્રન્ટના દેખાવો દોરો.				
	2	Draw the following piping symbols.	4			
		નીચેના પાઈપીંગના સંકેતો દોરો.				
		(1) ટી. (2) એલ્બો (3) યુનિયન (4) રીડ્યુસર				
Q-6		નીચેના પ્રશ્નોના જવાબ આપો.				
	1	નકલ જોઈન્ટના વિસ્તૃત (ડીટેઈલ) ભાગો આઈસોમેટ્રિક ડ્રોઈંગ દ્વારા આકૃતિ ૧ માં બતાવ્યા છે. તેના	10			
		અસેમ્બ્લી ડ્રોઈંગ તૈયાર કરો.				
	2	ફીટસના પ્રકારો લખી સમજાવો.	4			
Q-7		નીચેના પ્રશ્નોના જવાબ આપો.				
	1	આકૃતિ 2 એ સ્લીવ સાથે કોકર જોઈન્ટની સંયુક્તના એસેમ્બલી ડ્રોઈંગને બતાવે છે, તેના	10			
		વિગતવાર(ડીટેઈલ) ડ્રોઈંગને તૈયાર કરો.				
	2	AutoCADના ઓછામાં ઓછા ચાર કમાન્ડો લખી તેના ઉપચોગ લખો.	4			
	-	Amocadon બાર્ટાના બાર્ટા વાર કનાન્ડા લેખા તેમાં ઉપવાગ લેખા.	•			
Q-8		નીચેના પ્રશ્નોના જવાબ આપો.				
~ 0	1	ગાવના પ્રજ્ઞાના કવાલ આવા. વેલ્ડીંગ માટે સંપૂર્ણ માહિતી દર્શાવવા માટે ઉપયોગમાં લેવાતી સિમ્બોલ દોરો અને સિમ્બોલમાં બધી	10			
	_	માહિતીનો ઉલ્લેખ કરો.				
	_					
	2	નીચેના વેલ્ડિંગના સંકેત દોરો.	4			






Fig. 1




Fig.2

Page 6 || 6

