## C U SHAH UNIVERSITY

Diploma (Mechanical Engineering)

Sem: IV

Subject: Thermal Engieering-I

## English

Q-1		Explain Following Terms	14
	(A)	Sensible heat	
	(B)	Critical point	
	(C)	Degree of superheat  Mountings of hoiler	
	(D)	Mountings of boiler Accessories of boiler	
	(E)		
	(F)	Draught Equivalent evaporation	
	(G)	Impulse turbine	
	(H) (I)	Compounding of steam turbine	
	(I) (J)	Vacuum efficiency of condenser	
	(K)	Cooling tower	
	(K) (L)	Inter-cooling	
	(L) (M)	Black body	
	(N)	Emissive power	
	(11)	Attempt any four questions from following.	
Q-2	(A)	Explain Babcock-Wilcox boiler with neat sketch.	7
Q 2	(B)	Why compounding is necessary in steam turbine? List different methods of	7
	( <b>D</b> )	compounding and explain any one method with sketch.	,
Q-3	(A)	List the boiler mountings and accessories with their functions and	7
	` /	locations.	
	(B)	Write purpose of steam condenser and explain surface condenser with	7
	, ,	sketch. State advantages & disadvantages of it.	
Q-4	(A)	Classify cooling tower and explain induced draft cooling tower with	7
		sketchalso state advantages & disadvantages of it.	
	(B)	During a boiler trial, 2257 Kg/hr of steam having the dryness fraction = 0.8	7
		was produced using 300 Kg/hr of coal. If boiler pressure= 10bar and the	
		feed water temp =30 °C& Calorific value of coal = 30,000 KJ/Kg;	
		Calculate (1) Equivalent Evaporation (2) Thermal Efficiency (3) Boiler	
		Power.	
Q-5	(A)	Explain working of single stage reciprocating air compressor with sketch.	7
	(B)	A reciprocating compressor, compresses air from 1 bar pressure to 7 bars	7
		pressure. If Clearance volume = 2130 cm <sup>3</sup> /sec and compression obeys rule	
		$PV^{1.3} = C \& volumetric efficiency = 85\%$ then Calculate stroke volume in	
0.6	<i>(</i> <b>A</b> )	cm <sup>3</sup> /sec.	_
Q-6	(A)	State seven advantages of multistage compression over single stage compression.	7
	(B)	In a compressor, air is compressed from 1 bar pressure to 8 bar pressure at	7
		the rate of $0.5 \text{ m}^3/\text{min}$ . If isothermal efficiency = 75 %. Calculate Indicated	,
		power of compressor.	
Q-7	(A)	Explain various modes of heat transfer and differentiate between Free	7
	` /	1	

Q-8	(B) (A) (B)	List seven common thermal insulation materials with application. State types of heat exchangers and write application of each of them. Calculate (1) Thermal resistance (2) heat transfer rate from following data: Inner & Outer temperature of furnace wall= $1000~^{0}$ C & $200~^{0}$ C respectively. Furnace wall thickness 50 cm, cross sectional area 2 m² and thermal conductivity K = $0.4~\text{W/mK}$ .	7 7 7
		ગુજરતી	
y-٩		નીચેનાપદોસમજાવો.	98
	(A)	સેન્સિબલફીટ	
	(B)	ક્રિટીકલપોઈન્ટ	
	(C)	ડીગ્રીઓફસુપરહીટ	
	(D)	બોઈલરમાઉન્ટીંગ્સ	
	(E)	બોઈલરએસેસરીઝ	
	(F)	ŞIŞZ	
	(G)	સમકક્ષબાષ્પીભવન	
	(H)	ઇમ્પલ્સટર્બાઈન	
	(I)	ટર્બાઈનનુંકમ્પાઉન્ડીંગ	
	(J)	કંડેન્સરનીવેક્યુમકાર્યદક્ષતા	
	(K)	કુલીંગટાવર	
	(L)	ઈન્ટરકુલીંગ	
	(M)	બ્લેકબોડી	
	(N)	એમિસિવપાવર	
		નીચેનાપ્રશ્નોપૈકીકોઇપણચારનાજવાબોલખો.	
й-5	(A)	બેબકોક – વિલકોક્ષબોઈલરઆકૃતિસહસમજાવો.	ٯ
	(B)	સ્ટીમટર્બાઈનમાંકમ્પાઉન્ડીંગશામાટેજરૂરીછે?કમ્પાઉન્ડીંગનીજૂદીજૂદીપધ્ધતિના	و
		નામલખીગમેતેએકઆકૃતિસહસમજાવો.	
<b>у</b> -3	(A)	બોઈલરમાઉન્ટીંગઅનેએસેસરીઝનાનામલખોઅનેતેનાસ્થાનઅનેકાર્યજણાવો.	و
	(B)	સ્ટીમકંડેન્સરનોહેતુલખોઅનેગમેતેએકઆકૃતિસહસમજાવોતથાતેનાફાયદાઅનેગે	و
		રફાયદાલખો.	
<b>y</b> -8	(A)	કૂલીંગટાવરનુંવર્ગીકરણકરોઅનેઈન્ડ્યુસડ્રાફ્ટકૂલીંગટાવરઆકૃતિસહસમજાવોત	و
		થાતેનાફાયદાઅનેગેરફાયદાલખો.	

Convection and Forced Convection.

	(B)	બોઈલસ્ટ્રાયલદરમિયાન,300Kg/hrકોલસાનાદહનદ્રારા0.8શુષ્કાંકધરાવતી 2257	و
		Kg/hrવરાળપેદાકરવામાઆવેછે. જોબોઈલરદબાણ = 10	
		barઅનેફીડવોટરતાપમાન = 30°C તથાકોલસાનીકેલોરીફીકવેલ્યુ = 30,000	
		KJ/Kgહોયતોનીયેનીવિગતોબોઈલરમાટેગણો. (૧) સમકક્ષઈવોપરેશન (૨)	
		ઉષ્મીયદક્ષતા (૩) બોઈલરપાવર.	
પ્ર-પ	(A)	સિંગલસ્ટેજરેસિપ્રોકેટીંગએરકોમ્પ્રેસરનુંકાર્યઆકૃતિસહસમજાવો.	و
	(B)	એકરેસિપ્રોકેટીંગએરકોમ્પ્રેસર,હવાને૧બારથી૭બારદબાણસુધીકોમ્પ્રેસકરેછે.	و
		જોક્લિયરન્સવોલ્યુમ =2130 cm³/sec હોયઅનેકોમ્પ્રેસન PV <sup>1.3</sup> =C	
		નિયમપ્રમાણેથતુંહોયઅનેવોલ્યુમેટ્રિકકાર્યદક્ષતા=85%	
		હ્રોયતોસ્ટ્રોકવોલ્યુમcm³/sec માંશોધો.	
પ્ર-૬	(A)	સિંગલસ્ટેજકોમ્પ્રેસનનીસરખમણીમાં મલ્ટીસ્ટેજકોમ્પ્રેસનનાસાતફાયદાજણાવો.	و
	(B)	રેસિપ્રોકેટિંગએરક્રોમ્પ્રેસરદ્રારાહ્વાને૧બારથી૮બારદબાણસુધી૦.૫m³/min	૭
		નાદરથીકોમ્પ્રેસકરવામાંઆવેછે. જોઆઈસોથર્મલકાર્યદક્ષતા૭૫%	
		હોયતોકોમ્પ્રેસરનોઇંડીકેટેડપાવરગણો.	
પ્ર-૭	(A)	ઉષ્માવિનિમયનીજૂદીજૂદીપધ્ધતિઓસમજાવોઅનેફ્રીતથાફોર્સક્ન્વેક્શનવચ્ચેનોત	و
		ફાવતલખો.	
	(B)	સાતસામાન્યથર્મલઈસ્યુલેશનમટીરિયલનાનામઉપયોગિતાસાથેલખો.	و
<b>y</b> -८	(A)	હીટએક્ષચેંજરના પ્રકારોજણા વોઅને દરેકની ઉપયોગિતાલખો.	و
	(B)	નીચેનીવિગતોપરથી (૧) થેર્મલરઝીસ્ટન્સ (૨)	و
		ઉષ્માવિનીમયદરશોધો.ભદ્રીનીદિવાલનુંઆંતરિકતશાબાહ્યસપાટીનુંઅનુક્રમેતાપ	
		માન1000 ° C અને200 ° Cછે. ભક્ષીનીદિવાલનીજાડાઈ50 cm	
		તથાઆડછેદનુંક્ષેત્રફળ $2~\mathrm{m}^2$ તથાદિવાલનીથર્મલકંડક્ટીવિટી $\mathrm{K}=0.4~\mathrm{W/mK}$ છે.	